

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Information

---

Page Last Modified: 03/17/2016

**Building Information**

**1. Name of School District:**

BROCKPORT CSD

**2. SED District 8-Digit BEDS Code:**

261801060000

**3. Building Name:**

Brockport Concession Building

**4. SED 4-Digit Facility Code:**

7015

**5. Survey Inspection Date:**

09/02/2015

**6. Building 911 Address:**

40 Allen Street Building 202

**7. City:**

Brockport

**8. Zip Code:**

14420

**9. Certificate of Occupancy Status:**

- A - Annual
- T - Temporary
- N - None

**10. Certificate of Occupancy Expiration Date:**

01/01/2017

**Building Age, Gross Square Footage and Maintenance Staff**

**11. Year of Original Building:**

2006

**12. Gross square ft. of Building as currently configured:**

2,770

**13. Number of Floors:**

1

**14. How many full-time and part-time custodians are employed at the school (or work in the building)?**

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Information

Page Last Modified: 03/17/2016

	Count Employees
Full-time custodians:	0
Part-time custodians:	0
<b>Totals:</b>	

**Building Ownership and Occupancy Status**

**15. Building Ownership (check one):**

- Owned and used by district
- Owned by District and leased to non-district entity
- Owned by District, part used by district, part leased to non-district entity
- Owned by non-district entity and leased to district

**16. For which of the following purposes is the building currently used? (check all that apply)**

- Used for student instructional purposes
- Used for district administration
- Used for other district purposes
- Used by other organization(s)

**16a. Describe use for other district purposes:**

Refreshment stand and restrooms.

**Building Users**

**17. How many students were registered to receive instruction in this building as of October 1, 2014? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)**

0

**18. Of these registered students, how many receive most of their instruction in:**

	Quantity
18a. Permanent instructional spaces (i.e., regular classrooms)	0
18b. Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	0
18c. Non-instructional spaces used as instructional spaces	0

**18c.1 If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2014? (check all that apply)**

- Cafeteria
- Gymnasium
- Administrative Spaces
- Library
- Lobby
- Stairwell
- Storage space
- Other (please describe)
- None

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Information

---

Page Last Modified: 03/17/2016

**19. Grades Housed:**

N/a

**20. For how many instructional days during the 2013-14 school year (July 1 through June 30, was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")**

0

**21. Is the building used for instructional purposes in the summer?**

- Yes
- No

**22. Have there been renovations or construction in the building during the past 12 months?**

- Yes
- No

**23. Was major construction/renovation work since 2010 conducted when school was in session?**

- Yes
- No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Program Spaces

Page Last Modified: 03/17/2016

**Program Spaces**

**24. Number of instructional classrooms:**

0

**25. Gross square footage of all instructional classrooms (combined):**

0.00

**26. Other spaces provided: (check all that apply)**

- |   |   |   |
|---|---|---|
| <input checked="" type="checkbox"/> a. N/A (none) | <input type="checkbox"/> j. Health Office           | <input type="checkbox"/> s. Resource Rooms          |
| <input type="checkbox"/> b. Administration        | <input type="checkbox"/> k. Home & Careers          | <input type="checkbox"/> t. Science Labs            |
| <input type="checkbox"/> c. Art                   | <input type="checkbox"/> l. Kitchen                 | <input type="checkbox"/> u. Special Education       |
| <input type="checkbox"/> d. Audio Visual          | <input type="checkbox"/> m. Large Group Instruction | <input type="checkbox"/> v. Swimming Pool           |
| <input type="checkbox"/> e. Auditorium            | <input type="checkbox"/> n. Library                 | <input type="checkbox"/> w. Teacher Resource        |
| <input type="checkbox"/> f. Cafeteria             | <input type="checkbox"/> o. Multipurpose Rooms      | <input type="checkbox"/> x. Technology/Shop         |
| <input type="checkbox"/> g. Computer Room         | <input type="checkbox"/> p. Music                   | <input type="checkbox"/> y. Other (please describe) |
| <input type="checkbox"/> h. Guidance              | <input type="checkbox"/> q. Pre-K                   |   |
| <input type="checkbox"/> i. Gymnasium             | <input type="checkbox"/> r. Remedial Rooms          |   |

**26y. Describe other spaces**

(No Response)

**Space Adequacy**

**27. Rating of space adequacy:**

- Good
- Fair
- Poor

**27a. Enter comments:**

(No Response)

**28. Estimated capital construction expenses anticipated for this building through 2020-2021 school year excluding maintenance (to be answered after the building inspection is complete) \$**

15,312.00

**29. Overall building rating (to be answered after the building inspection is complete)**

- Excellent
- Satisfactory
- Unsatisfactory
- Poor

**30. Was overall building rating established after consultation with health and safety committee?**

- Yes
- No

**A/E Information:**

**31. A/E Firm Name:**

Labella Associates, DPC

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Program Spaces

---

Page Last Modified: 03/17/2016

**32. A/E Firm Address:**

300 State Street, Suite 201  
Rochester, Ny 14614

**33. A/E Firm Phone Number:**

5854546110

**34. E-mail:**

dpieters@labellapc.com

**35. A/E Name:**

Daniel Pieters

**36. A/E License #:**

032927

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Site Utilities

Page Last Modified: 03/17/2016

**Site Utilities**

**37. Water**

- Yes
- No

**37a. Type of Service:**

- Municipal or Utility provided
- Well
- Other

**37b. Condition:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**37c. Year of Last Major Reconstruction/Replacement:**

2006

**37d. Expected Remaining Useful Life (Years):**

20

**37e. Cost to Reconstruct/Replace \$:**

(No Response)

**37f. Comments:**

(No Response)

**38. Site Sanitary (H)**

- Yes
- No

**38a. Type of Service:**

- Municipal or utility sewer
- Site septic
- Other

**38b. Condition:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**38c. Year of Last Major Reconstruction/Replacement:**

2006

**38d. Expected Remaining Useful Life (Years):**

20

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Site Utilities

Page Last Modified: 03/17/2016

**38e. Cost to reconstruct/Replace \$:**

(No Response)

**38f. Comments:**

(No Response)

**39. Site Gas (H)**

- Yes
- No

**40. Site Fuel Oil (H)**

- Yes
- No

**41. Site Electrical, Including Exterior Distribution (H)**

- Yes
- No

**41a. Service Provider:**

- Municipal or utility provided
- Self-Generated
- Other
- N/A

**41b. Type of Service:**

- Above Ground
- Below Ground
- N/A

**41c. Condition:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**41d. Year of Last Major Reconstruction/Replacement:**

2006

**41e. Expected Remaining Useful Life (Years):**

25

**41f. Cost to Reconstruct/Replace \$:**

(No Response)

**41g. Comments:**

Fed from old concession stand under grandstand from High School.

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Site Utilities

Page Last Modified: 03/17/2016

**Stormwater Management**

**42. Closed Drainage Pipe Stormwater Management System**

**42a. Does this facility have a closed pipe system?**

- Yes
- No

**43. Open Drainage Pipe Stormwater Management System**

**43a. Does this facility have an open stormwater system (ditch)?**

- Yes
- No

**44. Catch Basins/Drop Inlets/Manholes**

**44a. Does this facility have catch basins/drop inlets/manholes?**

- Yes
- No

**45. Culverts**

**45a. Does this facility have culverts?**

- Yes
- No

**46. Outfalls**

**46a. Does this facility have outfalls?**

- Yes
- No

**47. Infiltration Basins/Chambers**

**47a. Does this facility have infiltration basins/chambers?**

- Yes
- No

**48. Retention Basins**

**48a. Does this facility have retention basins?**

- Yes
- No



**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Site Utilities

---

Page Last Modified: 03/17/2016

**49. Wetponds**

**49a. Does this facility have wetponds?**

- Yes
- No

**50. Manufactured Stormwater Proprietary Units**

**50a. Does this facility have proprietary units?**

- Yes
- No

**51. Point of Outfall Discharge: (check all that apply)**

- Municipal storm sewer system
- Combined sewer system
- Surface Water
- On-site recharge
- Other (describe)
- Not Applicable

**52. Outfall Reconnaissance Inventory**

**Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?**

- Yes
- No
- Not Applicable

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Other Site Features

Page Last Modified: 03/17/2016

**Other Site Features**

**53. Pavement (Roadways and Parking Lots)**

- Yes
- No

**54. Sidewalks**

- Yes
- No

**54a. Type: (check all that apply)**

- Concrete
- Asphalt
- Paver
- Other

**54b. Condition:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**54c. Year of Last Major Reconstruction/Replacement:**

2006

**54d. Expected Remaining Useful Life (Years):**

20

**54e. Cost to Reconstruct/Replace \$:**

(No Response)

**54f. Comments:**

(No Response)

**55. Playgrounds and Playground Equipment**

- Yes
- No

**56. Athletic Fields and Play Fields**

- Yes
- No

**56f. Does the facility have synthetic turf field(s)**

- Yes
- No

**56f.1 If Yes, how many synthetic turf fields?**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Other Site Features

---

Page Last Modified: 03/17/2016

**56f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):**

(No Response)

**56f.3 Type of synthetic turf field infill:**

(No Response)

**57. Exterior Bleachers / Stadiums**

Yes

No

**58. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)**

Yes

No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Substructure

Page Last Modified: 03/17/2016

**Substructure**

**59. Foundation (S)**

**59a. Type (check all that apply):**

- Reinforced Concrete
- Masonry on Concrete Footing
- Other

**59b. Evidence of structural concerns (check all that apply):**

- Structural Cracks
- Heaving/Jacking
- Decay/Corrosion
- Water Penetration
- Unsupported Ends
- Other
- None

**59c. Condition:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**59d. Year of Last Major Reconstruction/Replacement:**

2000

**59e. Expected Remaining Useful Life (Years):**

70

**59f. Cost to Reconstruct/Replace \$:**

(No Response)

**59g. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Envelope

Page Last Modified: 03/17/2016

**BUILDING ENVELOPE**

**60. Structural Floors (S)**

**60a. Type (check all that apply):**

- Reinforced Concrete Slab on Grade
- Concrete/Metal Deck/Metal Joists
- Precast Concrete Structural System
- Wood Deck on Wood Trusses
- Wood Deck on Wood Joists
- Concrete Deck on Wood Structure
- Other (specify)

**60b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):**

- Structural Cracks
- Unsupported Ends
- Rot/Decay/Corrosion
- Deflection
- Seriously Damaged/Missing Components
- Other Problems
- None

**60b.1 Describe Other Problems:**

(No Response)

**60c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):**

- Cracks
- Deflection
- Rot/Decay/Corrosion
- None

**60d. Overall Condition of Structural Floors:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**60e. Year of Last Major Reconstruction/Replacement:**

2006

**60f. Expected Remaining Useful Life (Years):**

50

**60g. Cost to Reconstruct/Replace \$:**

(No Response)

**60h. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Envelope

Page Last Modified: 03/17/2016

**61. Exterior Walls/Columns (S)**

**61a. Material (check all that apply):**

- Concrete
- Masonry
- Steel
- Wood
- Other (specify)

**61b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.) (check all that apply):**

- Structural Cracks
- Rot/Decay/Corrosion
- Other Problems
- None

**61b.1 Describe Other Problems:**

(No Response)

**61c. Evidence of Concerns with Exterior Cladding (check all that apply):**

- Cracks/Gaps
- Inadequate Flashing
- Efflorescence
- Moisture Penetration
- Rot/Decay/Corrosion
- Other Problems
- None

**61c.1 Describe Other Problems:**

(No Response)

**61d. Overall Condition of Exterior Walls/Columns:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**61e. Year of Last Major Reconstruction/Replacement:**

2006

**61f. Expected Remaining Useful Life (Years):**

60

**61g. Cost to Reconstruct/Replace \$:**

(No Response)

**61h. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Envelope

Page Last Modified: 03/17/2016

**62. Chimneys (S)**

- Yes
- No

**63. Parapets (S)**

- Yes
- No

**63f. Comments:**

(No Response)

**64. Exterior Doors**

**64a. Overall Condition of Exterior Door Units:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**64b. Overall condition of exterior door hardware:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**64c. Do any exterior doors have magnetic locking devices?**

- Yes
- No

**64d. Safety/Security features are adequate?**

- Yes
- No

**64e. Year of Last Major Reconstruction/Replacement:**

2006

**64f. Expected Remaining Useful Life (Years):**

21

**64g. Cost to Reconstruct/Replace \$:**

(No Response)

**64h. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Envelope

Page Last Modified: 03/17/2016

**65. Exterior Steps, Stairs, Ramps (S)**

- Yes
- No

**66. Fire Escapes (S)**

**66a. Does This Facility Have One or More Fire Escapes?**

- Yes
- No

**67. Windows**

- Yes
- No

**Roof and Skylights (S)**

**68. Roof and Skylights (S)**

- Yes
- No

**68a. Type of roof construction (check all that apply):**

- Metal deck on metal trusses/joists
- Wood deck on wood trusses/joists
- Wood deck on metal trusses/joists
- Concrete on metal deck on metal trusses/joists
- Other (describe below)

**68a.1 Other roof construction type:**

(No Response)

**68b. Type of roofing material (check all that apply):**

- Single-ply membrane
- Built-up
- Asphalt shingle
- Pre-formed metal
- IRMA
- Slate
- Other (describe below)

**68b.1 Other roofing material:**

(No Response)

**68c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):**

- Structural cracks
- Unsupported ends
- Rot/Decay/Corrosion
- Deflection
- Seriously damaged/missing components
- Other concerns (describe)
- None



**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Envelope

Page Last Modified: 03/17/2016

**68c.1 Describe other concerns:**

(No Response)

**68d. Evidence of structural concerns with roof deck (check all that apply):**

- Cracks
- Deflection
- Rot/Decay/Corrosion
- None

**68e. Does this facility have skylights?**

- Yes
- No

**68f. Skylight material (check all that apply):**

- Plastic
- Glass
- Other
- N/A

**68g. Overall condition of skylights:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**68h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):**

- Failures/Splits/Cracks
- Rot/Decay/Corrosion
- Inadequate flashing/curbs/pitch pockets
- Inadequate or poorly functioning roof drains
- Evidence of water penetration/active leaks
- Other (specify)
- None

**68h.1 Specify other concerns:**

(No Response)

**68i. Overall Condition of Roof and Skylights:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**68j. Year of Last Major Reconstruction/Replacement:**

2006

**68k. Expected Remaining Useful Life (Years):**

20

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Building Envelope

---

Page Last Modified: 03/17/2016

**68l. Cost to Reconstruct/Replace \$:**

(No Response)

**68m. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Interior Spaces

Page Last Modified: 03/17/2016

**INTERIOR SPACES**

**69. Interior Bearing Walls and Fire Walls (S)**

- Yes
- No

**69a. Overall condition of interior bearing walls and fire walls:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-functioning
- Critical Failure

**69b. Year of Last Major Reconstruction/Replacement:**

2006

**69c. Expected Remaining Useful Life (Years):**

60

**69d. Cost to Reconstruct/Replace \$:**

(No Response)

**69e. Comments:**

(No Response)

**Other Interior Walls**

**70. Other Interior Walls**

- Yes
- No

**70a. Overall condition of other interior walls:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**70b. Year of Last Major Reconstruction/Replacement:**

2006

**70c. Expected Remaining Useful Life (Years):**

60

**70d. Cost to Reconstruct/Replace \$:**

(No Response)

**70e. Comments:**

(No Response)

**Floor Finishes**

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Interior Spaces

Page Last Modified: 03/17/2016

**71. Carpet**

- Yes
- No

**72. Resilient Tiles or Sheet Flooring**

- Yes
- No

**73. Hard Flooring (concrete; ceramic tile; stone; etc)**

- Yes
- No

**73a. Where located (check all that apply):**

- Instructional Space
- Common Area

**73b. Overall condition of hard flooring:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**73c. Year of Last Major Reconstruction/Replacement:**

2006

**73d. Expected Remaining Useful Life (Years):**

20

**73e. Cost to Reconstruct/Replace \$:**

(No Response)

**73f. Comments:**

(No Response)

**74. Wood Flooring**

- Yes
- No

**Ceilings (H)**

**75. Ceilings (H)**

- Yes
- No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Interior Spaces

Page Last Modified: 03/17/2016

**75a. Overall condition of ceilings:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**75b. Year of Last Major Reconstruction/Replacement:**

2006

**75c. Expected Remaining Useful Life (Years):**

20

**75d. Cost to Reconstruct/Replace \$:**

(No Response)

**75e. Comments:**

(No Response)

**Lockers**

**76. Lockers**

- Yes
- No

**76d. Cost to Reconstruct/Replace \$:**

(No Response)

**Interior Doors**

**77. Interior Doors**

- Yes
- No

**77a. Overall condition of interior door units:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**77b. Overall condition of interior door hardware:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**77c. Year of Last Major Reconstruction/Replacement:**

2006

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey

Interior Spaces

Page Last Modified: 03/17/2016

77d. Expected Remaining Useful Life (Years):

20

77e. Cost to Reconstruct/Replace \$:

(No Response)

77f. Comments:

(No Response)

Interior Stairs (S)

78. Interior Stairs (S)

- Yes
- No

Elevator, Lifts and Escalators (H)

79. Elevator, Lift, and Escalators (H)

- Yes
- No

Interior Electrical Distribution (H)

80. Interior Electrical Distribution (H)

- Yes
- No

80a. Interior electrical supply meets current needs:

- Yes
- No

80b. Condition of interior electrical distribution:

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

80c. Year of Last Major Reconstruction/Replacement:

2006

80d. Expected Remaining Useful Life (Years):

20

80e. Cost to Reconstruct/Replace \$:

(No Response)

80f. Comments:

(No Response)

Lighting Fixtures

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Interior Spaces

Page Last Modified: 03/17/2016

**81. Interior Lighting Fixtures**

- Yes
- No

**81a. Condition of interior lighting fixtures:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**81b. Year of Last Major Reconstruction/Replacement:**

2006

**81c. Expected Remaining Useful Life (Years):**

15

**81d. Cost to Reconstruct/Replace \$:**

(No Response)

**81e. Comments:**

(No Response)

**Communication Systems (H)**

**82. Communication Systems (H)**

- Yes
- No

**82a. Communication systems are adequate:**

- Yes
- No

**82b. Condition of communication systems:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**82c. Year of Last Major Reconstruction/Replacement:**

2006

**82d. Expected Remaining Useful Life (Years):**

15

**82e. Cost to Replace/Reconstruct \$:**

(No Response)

**82f. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Interior Spaces

---

Page Last Modified: 03/17/2016

**Swimming Pool and Swimming Pool Systems**

**83. Swimming Pool and Swimming Pool Systems**

- Yes
- No



**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Plumbing (Excluding HVAC Systems)

Page Last Modified: 03/17/2016

**PLUMBING**

**84. Water Distribution System (H)**

- Yes
- No

**84a. Types of pipes (check all that apply):**

- Iron
- Galvanized
- Copper
- Lead
- PVC
- Other

**84b. Overall condition of water distribution system:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**84c. Year of Last Major Reconstruction/Replacement:**

2006

**84d. Expected Remaining Useful Life (Years):**

31

**84e. Cost to Reconstruct/Replace \$:**

(No Response)

**84f. Comments:**

(No Response)

**Plumbing Drainage System (H)**

**85. Plumbing Drainage System (H)**

- Yes
- No

**85a. Types of pipes (check all that apply):**

- Iron
- Galvanized
- Copper
- Lead
- PVC
- Other

**85b. Overall condition of drainage system:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Plumbing (Excluding HVAC Systems)

Page Last Modified: 03/17/2016

**85c. Year of Last Major Reconstruction/Replacement:**

2006

**85d. Expected Remaining Useful Life (Years):**

31

**85e. Cost to Reconstruct/Replace \$:**

(No Response)

**85f. Comments:**

(No Response)

**Hot Water Heaters (H)**

**86. Hot Water Heaters (H)**

- Yes
- No

**86a. Type of fuel (check all that apply):**

- Oil
- Natural Gas
- Electricity
- Propane
- Other

**86b. Overall condition of hot water heaters:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**86c. Year of Last Major Reconstruction/Replacement:**

2006

**86d. Expected Remaining Useful Life (Years):**

31

**86e. Cost to Reconstruct/Replace \$:**

(No Response)

**86f. Comments:**

(No Response)

**Plumbing Fixtures**

**87. Plumbing Fixtures**

- Yes
- No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Plumbing (Excluding HVAC Systems)

---

Page Last Modified: 03/17/2016

**87a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, etc):**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**87b. Year of Last Major Reconstruction/Replacement:**

2006

**87c. Expected Remaining Useful Life (Years):**

31

**87d. Cost to Reconstruct/Replace \$:**

(No Response)

**87e. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

HVAC Systems

Page Last Modified: 03/17/2016

**HVAC SYSTEMS**

**88. HVAC Systems Type**

**88a. Does this building have a central HVAC system?**

- Yes
- No

**Heat Generating Systems (H)**

**88b.1 Other central HVAC system technology:**

(No Response)

**89. Heat Generating Systems (H)**

- Yes
- No

**89a.1 Other heat generation source:**

(No Response)

**Heating Fuel/Energy Systems (H)**

**90. Heating Fuel / Energy Systems (H)**

- Yes
- No

**Cooling/Air Conditioning Generating Systems**

**91. Cooling / Air-Conditioning Generating Systems**

- Yes
- No

**AIR HANDLING AND VENTILATION EQUIPMENT**

**92. Air Handling and Ventilation Equipment: Supply Units, Exhaust Units, Relief/Return Units, etc. (H)**

- Yes
- No

**92a. Overall condition of air handling and ventilation systems:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**92b. Year of Last Major Reconstruction/Replacement:**

2006

**92c. Expected Remaining Useful Life (Years):**

10

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

HVAC Systems

Page Last Modified: 03/17/2016

**92d. Cost to Reconstruct/Replace \$:**

(No Response)

**92e. Comments:**

(No Response)

**Piped Heating and Cooling Distribution Systems**

**93. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectorss, Traps, Insulation, etc. (H)**

- Yes
- No

**Ducted Heating and Cooling Distrbution Systems**

**94. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)**

- Yes
- No

**HVAC Control Systems**

**95. HVAC Control Systems (H)**

- Yes
- No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Fire Safety Systems

Page Last Modified: 03/17/2016

**Fire Safety Systems**

**96. Fire Alarm Systems (H)**

- Yes
- No

**Smoke Detection System (H)**

**97. Smoke Detection Systems (H)**

- Yes
- No

**Fire Suppression Systems**

**98. Fire Suppression Systems: Sprinklers, Standpipes, Kitchen Hoods, etc. (H)**

- Yes
- No

**Emergency/Exit Lighting Systems**

**99. Emergency / Exit Lighting Systems (H)**

- Yes
- No

**99a. Overall condition of emergency / exit lighting systems:**

- Excellent
- Satisfactory
- Unsatisfactory
- Non-Functioning
- Critical Failure

**99b. Year of Last Major Reconstruction/Replacement:**

2006

**99c. Expected Remaining Useful Life (Years):**

15

**99d. Cost to Reconstruct/Replace \$:**

(No Response)

**99e. Comments;**

(No Response)

**Emergency/Standby Power Systems**

**100. Emergency or Standby Power System (H)**

- Yes
- No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Accessibility

Page Last Modified: 03/17/2016

**ACCESSIBILITY**

**101. Exterior Accessible Route (H)**

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

- Yes
- No

**102. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)**

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an accessible interior route as specified above?

- Yes
- No

**103. Additional Information on Accessibility**

If the building lacks accessible interior or exterior routes:

**103a. Cost of improvements needed to provide accessible exterior and interior routes as specified above \$:**

(No Response)

**103b. Comments:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Environment/Comfort/Health

Page Last Modified: 03/17/2016

**ENVIRONMENT/COMFORT/HEALTH**

**104. General Appearance**

**104a. Overall Rating:**

- Good
- Fair
- Poor

**104b. Comments:**

(No Response)

**105. Cleanliness**

**105a. Overall Rating:**

- Good
- Fair
- Poor

**105b. Comments:**

(No Response)

**106. Are there walk off mats; grills in the entryway?**

- Yes
- No

**107. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education?**

- Yes
- No

**108. Lighting Quality:**

**108a. Types of lighting in general purpose classrooms (check all that apply):**

- Daylight
- Flourescent-not full spectrum
- Flourescent full spectrum
- Incandescent
- Other (describe)

**108a.1 Describe Other:**

No classrooms

**108b. Are there blinds in the classroom to prevent glare?**

- Yes
- No

**108c. Overall Rating:**

- Good
- Fair
- Poor



**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Environment/Comfort/Health

---

Page Last Modified: 03/17/2016

**108d. Comments:**

(No Response)

**109. Evidence of Vermin**

**109a. Is there evidence of active infestations of...(check all that apply)?**

- Rodents
- Wood-boring or Wood-eating Insects
- Cockroaches
- Other Vermin
- None

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Indoor Air Quality

Page Last Modified: 03/17/2016

**Indoor Air Quality**

**110. Mold**

**110a. Is there visible mold or moldy odors?**

- Yes
- No

**110c. Are any surfaces constructed of any of the following materials?**

- Paper-faced or gypsum products
- Cellulose products (typically ceiling tiles)

**110d. Estimated cost of necessary improvements \$:**

(No Response)

**110d. Comments:**

(No Response)

**111. Humidity/Moisture**

**111a. Overall rating of humidity/moisture condition in building:**

- Good
- Fair
- Poor

**111b. Are any of the following found in/or around classroom areas (check all that apply)?**

- Active leaks in roof
- Active leaks in plumbing
- Moisture condensation
- Visible stains or water damage
- None

**111c. Are any of the following found in/or around other areas (check all that apply)?**

- Active leaks in roof
- Active leaks in plumbing
- Moisture condensation
- Visible stains or water damage
- None

**112. Ventilation: fresh air intake locations, air filters, etc.**

**112a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?**

- Yes
- No

**112b. Is there accumulated dirt, dust or debris around fresh air intakes?**

- Yes
- No

**112c. Are fresh air intakes free of blockage?**

- Yes
- No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Indoor Air Quality

Page Last Modified: 03/17/2016

**112d. Is accumulated dirt, dust or debris in ductwork?**

- Yes
- No

**112e. Are dampers functioning as designed?**

- Yes
- No

**112f. Condition of air filters:**

- Good
- Fair
- Poor

**112g. Outside air is adequate for occupant load:**

- Yes
- No

**112h. Rating of ventilation/indoor air quality:**

- Good
- Fair
- Poor

**112i. Comments:**

(No Response)

**113. Indoor Air Quality (IAQ) Plan**

**113a. Does the school district use EPA's Tools for Schools program?**

- Yes
- No

**113c. Has the District assigned IAQ responsibilities to a designated individual?**

- Yes
- No

**113c.1 If Yes, what is their job title?**

Director of Buildings & Grounds

**114. Does the school practice IPM?**

- Yes
- No

**114a. Is vegetation kept one foot away from the building?**

- Yes
- No

**114b. Are crevices and holes in walls, floors and pavement sealed or eliminated?**

- Yes
- No

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

Indoor Air Quality

Page Last Modified: 03/17/2016

**114c. Is there a certified pesticide applicator on staff?**

- Yes
- No

**114d. Are pesticides used in the building?**

- Yes
- No

**114d.1 If Yes, how are they typically applied?**

- Spot treatment
- Area wide treatments

**114e. Are pesticides used on the grounds?**

- Yes
- No

**114e.1 If Yes, was an emergency exemption granted by the Board of Education?**

- Yes
- No

**115. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?**

- Yes
- No

**115a. Has the facility been tested for the presence of radon?**

- Yes
- No

**115b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?**

- Yes
- No

**115c. If Yes, did the school take steps to mitigate the elevated radon levels?**

- Yes, active mitigation system installed
- Yes, passive mitigation system made active
- Yes, ventilation controls (HVAC) adjusted
- Yes, other (describe)
- No action taken

**115c.1 Describe other actions taken to mitigate elevated radon levels:**

(No Response)

**2015 Building Condition Survey Instrument - 2015 Building Conditions Survey**

American Red Cross

---

Page Last Modified: 03/17/2016

**American Red Cross Shelter**

**116. American Red Cross Shelter**

Yes

No